

Auto CAD. — * Commands * —

* Line Command $\Rightarrow$ Line Command is used to allow certain a line, while the end points are specified by 2 dimensions or dimensions co-ordinates

To draw a Continuous line arrangement we make specified the point or Fix the point with the help of mouse

* Ex $\Rightarrow$ Command : Line $\leftarrow$

* specified 1st point : Pick (use of mouse gives the Points)

* specified next point : Pick

* specified next point : Close $\leftarrow$

The line can be drawn by co-ordinate system and they are classed as.

i) Absolute co-ordinate system

ii) Relative co-ordinate system $\Rightarrow$

a) Relative rectangular co-ordinate system
[@ x, dist, y dist]

b) Relative polar co-ordinate system
[@ dist, Langle]

* Absolute co-ordinate system $\Rightarrow$

It is specified by given the values of x by. The following sequences of co-ordinates to draw a triangle & rectangle as shown below


Command : L $\leftarrow$

specified 1st point : 8, 3 $\leftarrow$

specified next point : 7, 3 $\leftarrow$

specified next point : 5, 5 $\leftarrow$

specified next point : C $\leftarrow$



* Rectangular $\Rightarrow$

Command : L $\downarrow$


Specified 1st point : 2, 3 $\downarrow$

Specified next point : 6, 3 $\downarrow$

Specified next point : 6, 5 $\downarrow$

Specified next point : 2, 5 $\downarrow$

Specified next point : C $\downarrow$



* Relative Rectangular Co-ordinate system $\Rightarrow$

Here relative co-ordinate when you know the possible point with respect to previous, the relative rectangular co-ordinate is represented as $\Rightarrow$

Command : L $\downarrow$

Specified 1st point : 2, 2 $\downarrow$


Specified next point : @ 4, 0 $\downarrow$

Specified next point : @ 0, 4 $\downarrow$

Specified next point : @ -2, 0 $\downarrow$

Specified next point : @ 0, -2 $\downarrow$

Specified next point : @ -2, 0 $\downarrow$



* Relative Polar Co-ordinate system →

In this polar system we distance & an co-ordinate with reference to the previous point to locate a point "t" angle are measured in anticlockwise direction, Polar system represented as [@ distance, angle]

* Ex ⇒ Command : L ↵


specified 1st point : 2,3 ↵

specified next point : @ 4,10 ↵

specified next point : @ 2,190 ↵

specified next point : @ 4,180 ↵

specified next point : @ 2,270 ↵



* Hexagon ⇒

Command : L ↵

specified 1st point : (2, 2)

specified next point : @ 3, 10 ↵


specified next point : @ 3, 160 ↵

specified next point : @ 3, 120 ↵

specified next point : @ 3, 180 ↵

specified next point : @ 3, 240 ↵

specified next point : C ↵



* Circle ⇒ Circle can be created in autocad by several methods, the default method is to specified a centre & radius.

* Ex: Command : C ↵

specified the centre point < 2p, 3p, ttr > : 3p

specified 1st point in the circle : Pick P1 ↵

specified 2nd point in the circle : Pick P2 ↵

specified 3rd point in the circle : Pick P3 ↵

* Break $\Rightarrow$ The break command is used to break the circuit or lines.

* Array $\Rightarrow$ i) Rectangular Array
ii) Polar Array.

when we used to make multiple copies of object but at mutual copy command is little cumbersome. Array command is easy a hardly includes situations it displayed and array dialogs where we set a number of rows, no. of columns etc.

* Mirror $\Rightarrow$

Sometimes we need to create objects that are symmetric about a particular axis in such cases mirror command is used.

We can draw one half of the model & autocad processed other half of the mirror. This way you can reduce your effort.


* Ex :- Command : mirror $\swarrow$

Select the object : By window $\swarrow$


Specify 1st point in the mirror line : Pick P1

Specify 2nd point in the mirror line : Pick P2

Select square object <Y/N> <Z> : $\swarrow$



- i) Draw a Single line diagram with following accessories →
- i) 2, 11 kv incoming lines connected to the busbars through circuit breakers and isolators.
 - ii) Two 400v outgoing lines are connected to the busbars through transformer of 11kv/400v.



1) Draw a single line diagram of a typical substation at the following demands $\Rightarrow$


- i) Two transformers 66 kV / 11 kV, 3 ϕ , 5 MVA $\Delta - \Delta$ connected
- ii) one auxiliary station transformer 11 kV / 400 V, 3- ϕ , 500 kVA, $\Delta - Y$ connection
- iii) Two incoming lines of 66 kV
- iv) One outgoing line of 66 kV
- v) Eight outgoing lines of 11 kV


Arrange the buses, CB's, disconnecting switches, CT's, PT's & also show the lightning arresters.

Draw a single line diagram of 66kV/11kV line having following data →

- i) Two 66kV incoming lines
- ii) Two busbars of 66kV
- iii) Two outgoing lines of 66kV
- iv) One bus coupler of 66kV of OCB
- v) Two transformers of 66kV/11kV, Y-Y connection.
- vi) Two 11kV busbars each having three 11kV outgoing lines & one coupled with bus coupler.


shows the CT, PT, lightning arrester in appropriate positions.





WINDINGS.

D C Armature Windings:



- $y_F \rightarrow$ Front Pitch
- $y_B \rightarrow$ Back pitch.
- $y_C \rightarrow$ Commutator Pitch.
- $y_R \rightarrow$ Resultant pitch.
- $y_P \rightarrow$ Pole pitch.

POLE PITCH:— Number of ~~poles~~ ^{conductors} under the poles. or no. of conductors per pole is known as pole pitch.

Ex:- If 24 conductors in a armature & with 4 pole. Then pole

$$\text{pitch} = \frac{24}{4} = 6$$

Front pitch:— The ~~conductor~~ distance covered by the front end connections in terms of conductors. It is called front pitch & it is denoted by " y_F ".

BACK PITCH:— (y_B):— The distance covered by the end connection of the conductors (coil sides). is known as back pitch & it is denoted by " y_B ".

RESULTANT PITCH:— (y_R):— Defined as the distance between the start of one coil and the start of the next coil to which it is connected. It is also known as winding pitch or Resultant pitch (y_R). It is denoted by " y_R ".

Commutator Pitch:- (γ_c):- The distance measured in terms of commutator segments between the two ends of a coil are connected. Ex - For Simplex winding - $\gamma_c = 1$
Duplex winding - $\gamma_c = 2$

FULL PITCH:- If the coil pitch is equal to the pole pitch then the winding is said to be "full pitch winding".

Short Pitch winding / short chorded winding:- If the coil pitch is not equal to the pole pitch. If it is short then the winding is called short chorded winding.

In such winding the copper required is less, hence copper loss is ~~less~~ will be less due to short end connections & harmonics become less.

SINGLE LAYER WINDING:- It is winding, in which only one conductor / coil side is placed in each slot.

DOUBLE LAYER WINDING:- It is the winding, in which two conductors / coil sides are placed in each slot. Usually one side of coil lies in the upper half of one slot & another side lies in the lower half of some other slot.

Conditions of Lap Winding

- $$\text{ie } Y_a = \frac{Y_b + Y_f}{2} = \frac{Z}{P}$$

c) $Y_B = Y_f \pm 2Y_c$.

- For a simplex lap winding, $y_c = 1$.

$$\therefore y_b = y_f \pm 2 \quad \text{or} \quad y_b - y_f = \pm 2$$

- Equilisers for Lap Winding:- In a lap winding no. of 1/1st paths = No. of poles

$$\text{No. of equalizer rings} = \frac{\text{No. of coil-sides/pole}}{2}$$

Ex. 1 Design & draw a developed winding diagram for a 16 slots, double layer 4-pole, DC progressive, simplex lap winding. Make provision for equalizer rings.

Soln:- No. of conductors or coil sides = $Z = 16 \times 2 = 32$, $P = 4$ poles.

$$Y_a = \frac{Y_b + Y_f}{2} = \frac{Z}{P} = \frac{32}{4} = 8 \quad \therefore \frac{Y_b + Y_f}{2} = 8 \quad \text{ie } Y_b + Y_f = 16$$

For a simplex progressive lap winding

$$Y_b - Y_f = 2 \quad \text{--- (1)}$$

$$Y_b + Y_f = 16 \quad \text{--- (2)}$$

Adding these equations.


$$2Y_b = 18$$

$$\therefore Y_b = 9 \text{ \& } Y_f = 7$$

$$\text{No. of equalizer rings} = \frac{\text{No. of coil-sides/pole}}{2}$$

$$\frac{Z}{2P} = \frac{32}{2 \times 4} = 4$$

$$\text{No. of connections each equalizer ring} = \text{No. of pairs of poles} = 2$$



1) Draw & design a developed winding diagram for a 16 slots double layer . 4 Pole . Dc progressive, simplex lap winding.

Soln :->

There is a double layer winding hence,
No. of conductors = $Z = \text{slots} \times 2 = 16 \times 2$
 $\therefore \boxed{Z = 32}$ conductors.

* Here , $P = 4$

$$\therefore Y_a = \frac{Y_b + Y_F}{2} = \frac{Z}{P} = \frac{32}{4} = 8$$

$$\therefore Y_b + Y_F = 8 \times 2 \Rightarrow \boxed{Y_b + Y_F = 16}$$

* For Simplex Progressive lap winding $\Rightarrow$

$$Y_b - Y_F = 2 \quad \text{--- (1)}$$

$$Y_b + Y_F = 16 \quad \text{--- (2)}$$


$$2 Y_b = 18$$

$$\therefore \boxed{Y_b = 9}$$

$$\& 9 + Y_F = 16 \Rightarrow Y_F = 16 - 9 \Rightarrow \boxed{Y_F = 7}$$

* winding Table $\Rightarrow$

At the back $Y_b = 9$ coil connected Side $\rightarrow$ Coil Side	At the Front $Y_F = 7$ coil connected Side $\rightarrow$ Coil Side	At the back $Y_b = 9$ coil connected Side $\rightarrow$ Coil Side	At the Front $Y_F = 7$ coil connected Side $\rightarrow$ Coil Side
$1 + 9 = 10$	$10 - 7 = 3$	$15 + 9 = 24$	$24 - 7 = 17$
$3 + 9 = 12$	$12 - 7 = 5$	$17 + 9 = 26$	$26 - 7 = 19$
$5 + 9 = 14$	$14 - 7 = 7$	$19 + 9 = 28$	$28 - 7 = 21$
$7 + 9 = 16$	$16 - 7 = 9$	$21 + 9 = 30$	$30 - 7 = 23$
$9 + 9 = 18$	$18 - 7 = 11$	$23 + 9 = 32$	$32 - 7 = 25$
$11 + 9 = 20$	$20 - 7 = 13$	$25 + 9 = 34(2)$	$34 - 7 = 27$
$13 + 9 = 22$	$22 - 7 = 15$	$27 + 9 = 36(4)$	$36 - 7 = 29$
		$29 + 9 = 38(6)$	$38 - 7 = 31$
		$31 + 9 = 40(8)$	$40 - 7 = 33(1)$



- 2) Draw a armature winding of a DC machine with 4 pole, 14 slots, double layer progressive lap winding shows the position of brush & direction of induced EMF.

$$\Rightarrow \text{No. of conductors} = Z = 14 \times 2 = 28 \quad \& \quad P = 4$$

$$* Y_a = \frac{Y_b + Y_f}{2} = \frac{Z}{P} = \frac{28}{4} = 7 //$$

$$\therefore Y_b + Y_f = 7 \times 2 = 14$$

* For Simplex progressive lap winding

$$Y_b - Y_f = 2 \quad \text{--- ①}$$

$$Y_b + Y_f = 14 \quad \text{--- ②}$$

$$2Y_b = 16 \Rightarrow Y_b = 16/2$$

$$\therefore Y_b = 8$$


$$* Y_f = Y_b - 2 \Rightarrow 8 - 2 \Rightarrow Y_f = 6$$

* Here, Y_b & Y_f are even so we can take odd numbers i.e. $Y_b = 7$ & $Y_f = 5$

* winding Table $\Rightarrow$

At the back $Y_b = 7$ coil connected $\rightarrow$ coil side	At the front side $Y_f = 5$ coil connected $\rightarrow$ coil side	At the back side $Y_b = 7$ coil connected $\rightarrow$ coil side	At front side $Y_f = 5$ coil connected $\rightarrow$ coil side
$1 + 7 = 8$	$8 - 5 = 3$	$21 + 7 = 28$	$28 - 5 = 23$
$3 + 7 = 10$	$10 - 5 = 5$	$23 + 7 = 30 (2)$	$30 - 5 = 25$
$5 + 7 = 12$	$12 - 5 = 7$	$25 + 7 = 32 (4)$	$32 - 5 = 27$
$7 + 7 = 14$	$14 - 5 = 9$	$27 + 7 = 34 (6)$	$34 - 5 = 29 (1)$
$9 + 7 = 16$	$16 - 5 = 11$		
$11 + 7 = 18$	$18 - 5 = 13$		
$13 + 7 = 20$	$20 - 5 = 15$		
$15 + 7 = 22$	$22 - 5 = 17$		
$17 + 7 = 24$	$24 - 5 = 19$		
$19 + 7 = 26$	$26 - 5 = 21$		

PRODUCED BY AN AUTODESK EDUCATIONAL PRODUCT



- 3) Draw the developed winding diagram for 6 pole, 18 slots, double layer Full pitch lap wound DC generator. Draw the sequence diagram. Fix the position & polarity of brush. Mark the direction of armature.

⇒

There is a double layer winding hence,
No. of conductor = $Z = 18 \times 2 = 36$ // & $P = 6$.

$$\therefore Y_a = \frac{Y_b + Y_F}{2} = \frac{Z}{P} = \frac{36}{6} = 6 //$$

$$\therefore Y_b + Y_F = 6 \times 2 = 12 //$$

* For Simplex progressive lap winding ⇒

$$Y_b - Y_F = 2$$

$$Y_b + Y_F = 12$$


$$2Y_b = 14 \Rightarrow Y_b = 14/2$$

$$\therefore Y_b = 7$$


$$* Y_F = Y_b - 2 \Rightarrow Y_F = 7 - 2 \Rightarrow Y_F = 5$$

* Winding Table ⇒

At back side $Y_b = 7$ Coil Side → Coil connected Side	At Front Side $Y_F = 5$ Coil Side → Coil connected Side	At back side $Y_b = 7$ Coil Side → Coil connected Side	At Front Side $Y_F = 5$ Coil Side → Coil connected Side
$1 + 7 = 8$	$8 - 5 = 3$	$21 + 7 = 28$	$28 - 5 = 23$
$3 + 7 = 10$	$10 - 5 = 5$	$23 + 7 = 30$	$30 - 5 = 25$
$5 + 7 = 12$	$12 - 5 = 7$	$25 + 7 = 32$	$32 - 5 = 27$
$7 + 7 = 14$	$14 - 5 = 9$	$27 + 7 = 34$	$34 - 5 = 29$
$9 + 7 = 16$	$16 - 5 = 11$	$29 + 7 = 36$	$36 - 5 = 31$
$11 + 7 = 18$	$18 - 5 = 13$	$31 + 7 = 38(2)$	$38 - 5 = 33$
$13 + 7 = 20$	$20 - 5 = 15$	$33 + 7 = 40(4)$	$40 - 5 = 35$
$15 + 7 = 22$	$22 - 5 = 17$	$35 + 7 = 42(6)$	$42 - 5 = 37(1)$
$17 + 7 = 24$	$24 - 5 = 19$		
$19 + 7 = 26$	$26 - 5 = 21$		



a) developed winding diagram



b) sequence diagram

5) Design & draw a duplex winding diagram of a dc machine with 32 conductors & 4 poles. shows the direction of rotation of the motor.

⇒ In duplex windings, there are 2 simplex windings starts from 1 & 3 conductors.

* Here, $P = 4$ & $Z = 32$

$$\therefore Y_a = \frac{Y_b + Y_F}{2} = \frac{Z}{P} = \frac{32}{4} = 8 //$$

$$\therefore Y_b + Y_F = 8 \times 2 = 16 // \quad \text{--- (1)}$$

$$\& Y_b - Y_F = 2m = 2 \times 2$$

$$\therefore Y_b - Y_F = 4 \quad \text{--- (2)}$$

| $\therefore m = 2$ For duplex

* Hence,

$$Y_b - Y_F = 4$$

$$Y_b + Y_F = 16$$

$$2Y_b = 20 \Rightarrow Y_b = 20/2 \Rightarrow \boxed{Y_b = 10}$$


$$* Y_F = Y_b - 10 = 16 - 10 \Rightarrow \boxed{Y_F = 6}$$

* we can take the odd no. of Y_b & Y_F . hence

$$\boxed{Y_b = 9} \& \boxed{Y_F = 5}$$

* winding Table ⇒

1 st winding		2 nd winding	
At back $Y_b = 9$ Coil Side → Coil Connected Side	At front $Y_F = 5$ Coil Side → Coil Connected Side	At back $Y_b = 9$ Coil Side → Coil Connected Side	At front $Y_F = 5$ Coil Side → Coil Connected Side
$1 + 9 = 10$	$10 - 5 = 5$	$3 + 9 = 12$	$12 - 5 = 7$
$5 + 9 = 14$	$14 - 5 = 9$	$7 + 9 = 16$	$16 - 5 = 11$
$9 + 9 = 18$	$18 - 5 = 13$	$11 + 9 = 20$	$20 - 5 = 15$
$13 + 9 = 22$	$22 - 5 = 17$	$15 + 9 = 24$	$24 - 5 = 19$
$17 + 9 = 26$	$26 - 5 = 21$	$19 + 9 = 28$	$28 - 5 = 23$
$21 + 9 = 30$	$30 - 5 = 25$	$23 + 9 = 32$	$32 - 5 = 27$
$25 + 9 = 34(2)$	$34 - 5 = 29$	$27 + 9 = 36(4)$	$36 - 5 = 31$
$29 + 9 = 38(6)$	$38 - 5 = 33(1)$	$31 + 9 = 40(8)$	$40 - 5 = 35$



7) Design & draw 4 pole, double layer progressive wave winding with 17 slots double layer.

⇒ Here, double layer progressive wave winding.

∴ No. of conductor = $Z \times 2 = 17 \times 2 = 34$ & $P = 4$

$$Y_a = \frac{Y_b + Y_F}{2} = \frac{Z \pm 2}{P} = \frac{Z + 2}{P} = \frac{34 + 2}{4} = 9 //$$

$$= \frac{Z - 2}{P} = \frac{34 - 2}{4} = 8 //$$

* we can choose only odd values, hence,

$$Y_b = Y_F = 9$$


* winding Table ⇒

At the back $Y_b = 9$
coil side → coil connected side


$1 + 9 = 10$
 $19 + 9 = 28$
 $3 + 9 = 12$
 $21 + 9 = 30$
 $5 + 9 = 14$
 $23 + 9 = 32$
 $7 + 9 = 16$
 $25 + 9 = 34$
 $9 + 9 = 18$
 $27 + 9 = 36 (2)$
 $11 + 9 = 20$
 $29 + 9 = 38 (4)$
 $13 + 9 = 22$
 $31 + 9 = 40 (6)$
 $15 + 9 = 24$
 $33 + 9 = 42 (8)$
 $17 + 9 = 26$

At the front $Y_F = 9$
coil side → coil connected side.

$10 + 9 = 19$
 $28 + 9 = 37 (3)$
 $12 + 9 = 21$
 $30 + 9 = 39 (5)$
 $14 + 9 = 23$
 $32 + 9 = 41 (7)$
 $16 + 9 = 25$
 $34 + 9 = 43 (9)$
 $18 + 9 = 27$
 $2 + 9 = 11$
 $20 + 9 = 29$
 $4 + 9 = 13$
 $22 + 9 = 31$
 $6 + 9 = 15$
 $24 + 9 = 33$
 $8 + 9 = 17$
 $26 + 9 = 35 (1)$



a) developed winding diagram



b) sequence diagram

Example : 4

Draw to suitable scale half sectional elevation and half sectional plan of a single phase 120 KVA, 2000/400 V shell type transformer from given sketch.
Missing details are to be suitably assumed.





Fig. 5.25 : Given sketch
SHELL TYPE SINGLE PHASE TRANSFORMER

1 Phase Shell Type Transformer



The following are the details of three phase core type transformer drawn to suitable scale.

1. Elevation of transformer assembly showing one limb in section.
2. Plan of transformer assembly showing one limb in section.

a) Core :- 3 step construction

Core dia = 220 mm

height of core = 1180 mm

height of yoke = 250 mm

Centre to centre distance between limb = 350 mm

b) LV winding :-

Inside dia LV winding 231 mm

winding in two layer total radial thickness = 13.3 mm

Radial thickness of one layer = 7.4 mm

Thickness of LV former = 3 mm

No. of turn per layer = 13 mm

Total height of LV winding = 1127 mm

c) HT winding :-

Outside dia of HT winding = 340 mm

Total number of coils = 12



1. Two coils of end gem metal ring turn each of 14 mm thick

2. Ten coils of SG turns each (made from Upsee each 3 mm thick)

Total height of HT winding = 1127 mm

Average end clearance 33 mm from top and 20 mm from the bottom of the yoke.

PRODUCED BY AN AUTODESK EDUCATIONAL PRODUCT
3 PHASE CORE TYPE TRANSFORMER



Draw the front elevation left half in section, sectional plan and end view of a transformer with the dimensions given below. Scale $1/2$ full size. Single phase core type 15 kVA with distribution on type transformer.

Details of Magnetic Circuit :-

Cross section of Core $\approx 63 \text{ mm} \times 91.6 \text{ mm}$

Window $\approx 298.5 \text{ mm} \times 114.5 \text{ mm}$

Yoke height $\approx 63.5 \text{ mm}$

Details of Electrical Circuit :-

1. LV windings : No. of coils on each leg $= 1$

No. of turns per coils ≈ 72

No. of layers per coil ≈ 3

Section of Conductor $\approx 2.79 \text{ mm} \times 10.6 \text{ mm}$

2. HV winding : No. of coils on each leg ≈ 1

No. of turns per coils ≈ 720

No. of layers per coils ≈ 8

Cross section of wire $\approx 2.59 \text{ mm dia}$

Details of Dielectrical media :-

Air space around the core $\approx 1.66 \text{ mm}$


Insulation b/w core and LT $\approx 1.6 \text{ mm}$

Insulation on HT $\approx 3 \text{ mm}$

Insulation at the top and bottom winding and


insulation b/w layers $\approx 0.35 \text{ mm}$.

All dimensions are in mm provide 10 mm ball with sleeve at suitable spacing.



DC Motor With Inter Pole

PRODUCED BY AN AUTODESK EDUCATIONAL PRODUCT



Side Sectional Elevation

Front Sectional Elevation

Draw and design of DC motor with inter pole
 show the with suitable scale and also show
 i) Front sectional elevation
 ii) Side sectional elevation


EXAMPLE : 6

The accompanying sketch, gives the details of a D.C. machine armature. Draw the following assembled view of it, to full scale.

- Half sectional front elevation, showing top half in section.
- End elevation showing top half in section.

Solution Fig. 2.22.


DETAILS OF PARTS OF ARMATURE OF A D.C. MACHINE



NOTE : ALL DIMENSIONS ARE IN MM

Fig. 2.21 accompanying sketch


ARMATURE OF D.C. MACHINE



EXAMPLE : 11

The accompanying sketch shows the details of commutator parts. Draw the following view.
1. End elevation with top half in section 2. Front elevation with top half in section scale=Full scale,
Solution fig. 2.31

PARTS OF A COMMUTATOR
SKETCH IS NOT TO SCALE



Commutator segments 70x40x
1.5 mm Thick Insulation is pro-
vided between the Commutator
segments & supporting parts
(i.e. the sleeve and V ring)

ALL DIMENSIONS ARE IN MM






Fig. 2.30 accompanying sketch
PARTS OF A COMMUTATOR

PRODUCED BY AN AUTODESK EDUCATIONAL PRODUCT



PRODUCED BY AN AUTODESK EDUCATIONAL PRODUCT

LAMINATED FIELD POLY



